

# KTI Networks Important Notice

May 28, 2008

## PRODUCT


KGD-600

## FIRMWARE

Ver.1.24 or earlier

## PROBLEM

As two scenarios shown below, the Windows PC is unable to manage the Switch M via web browser or ping the Switch M through the Switch N if the Mac address M is within the range of N and N+6.



In both scenarios, the packet switching function on the Switch M and Switch N are with no problem but only management function.

## SOLUTION

Update the firmware of the Switch N with firmware **Ver.1.25**.